CLASSIFICATION L

CENTRAL INTELLIGENCE AGENC INFORMATION FROM FOREIGN DOCUMENTS OR RADIO BROADCASTS

REPORT CD NO.

50X1-HUM

COUNTRY

USSR

DATE OF

INFORMATION 1947.

SUBJECT Mineralogy - Nickel

HOW PUBLISHED Book DATE DIST.70 Jul 1949

WHERE

PUBLISHED Moscow

NO. OF PAGES 2

PUBLISHED 1947

LANGUAGE Russian

SUPPLEMENT TO

REPORT NO.

THIS IS UNEVALUATED INFORMATION

SOURCE

Motallurgiya nikolya, by Prof A.A. Isopilor, published by Metallurgizati

MICKEL SMELTING IN THE USSE

The first nickel plant, the Ufaley, was built in the Soviet Union in 1933. In 1936 another plant, the Rezhek, was built, and somewhat later the Crak plant (InUEK) came into existence. These plants work on oxidized ores.

For the processing of sulfide copper-nickel ores, the following plants were constructed: Soveronikel, Noril'sk, and Posnenge Mikel.

The Waley nickel plant is supplied with exidized nickel ore which is mined in Ufaley dayon. The nickel deposits on this area are still in the process of prospecting.

Because French specialists were in charge of construction of the Ufaley smelter, production methods at this plant are antiquated, being the same as the methods used at the New Caledonia plants. The work of the plant has proved defective in a number of respects. Several changes in the smalting process have been made, but essentially the character of the smelting methods remain the same.

In Movember 1936, the Rezhak nickel plant entered production, utilizing small local deposits of oxidized nickel ores of Rezhek Rayon. This plant uses a simplified method of smelting raw ore in a water jacket, without preparation with gypsum, limestone, and reverse slags. The raw metal thus obtained is poured into molds, and the ingots are sent to the Ufaley plant.

The Crek plant operates on oxidized nickel ores which are mined in Orsk-Thalilovo and Aktynbinsk rayons. Ore processing passes through the following stages: agglemeration by means of Dwight Lloyd machines, swelting the agglemerate in water jackets in a mixture of gypsum or pyritin tails, blowing the raw metal in converters, reasting the intermediate metal sulfide (feinstein) in mechanical ovens, smelting the oxide in electrical ovens, and pouring nickel into granules.

,					CLASSIFICATION CONFIDENTIAL								
	STATE	X	NAVY	$\exists x$	NSRB		TRIBUTION]
	ARMY	X	AIR	$\top \times$	FBI			1		\Box]
		_		F									

CONFIDENTIAL

50X1-HUM

The copper-nickel ores of the Kole Peninsula are processed at the Severonikel and Pechenga Nikel plants. Part of the ore is dressed while the rost goes into the oven in a raw state, owing to the scarcity of fuel in the region. The raw metal obtained is blown in a converter until it becomes feinstein. The feinstein is then processed by the Orford method. Rich nickel ores made up of large lumps are smelted in water jackets without preliminary dressing.

The Maril'sk copper-nickel ores are processed locally on account of the evailability of coal at Moril'sk. The high-quality are consisting of large lumps is smelted in water jackets by means of semipyritic smelting. On the other hand, the fine and low-grade impregnated ore goes through preliminary dressing. The concentrate, together with the dust and fines, is agglomerated in Dwight Lloyd machines, and is smelted in water jackets. The raw metal is blown in a converter to obtain feinstein which is processed locally by the Orford process. In the future, it is proposed to introduce the process of selective flotation, and elimate the Orford process.

Mickel ingots and granules are of two kinds: the metal may be obtained by recovering pure oxides of nickel in a mixture of charcoal, or by electrolytic qualiting. In the latter case, the metal is of considerably higher quality. The entire production of the Ufaley and Orak plants is of the first type. Metal is obtained by smelting oxides of nickel with coal.

Table 1. Standards of USSR Nickel

	N1 + CO	Including	Impurities Not More Than \$						
Grade	Not Less Than 5	Co Not Less Than %	7e	<u>81</u>	c	<u> 5</u>	. Cu		
H1	99.5	0.6	n.25	Traces	0.10	` @ .02	0.10		
H 2	98.5	1.0	0.60	0.15	0.15	0.03	0,25		
H3 Mà	99.5	1.0			0.30	0.03	0.60		
<u> </u>	97-5	1:0	~-		0.30	0.05	0.60		

The USER mickle does not contain the Mond fraction. The Mond fraction differs from electrolytic nickel rainly by a lower content of cobalt. This type of nickel is required only for thermoelectric alloys, and the USER standards do not provide for it.

A comparison of USSR nickel standards with those of foreign countries discloses a higher copper content in Soviet nickel due mainly to the fact that the nickel ares of the USSR are contaminated with copper to a larger extent than foreign ores.

Nickel Ores

There are three types of ores used in the smelting of nickel: oxidized (silicate)ores, sulfide copper-nickel ores, and arsenic.

The Ufaley and Rezhek deposits belong to the first type, and the Orsk and Aktyabinsk deposits to the second type. The third type is an iron-nicsel ore. When the iron content of this ore is sufficiently high, it is sent to the smelter for the production of alloyed pig. Iron-nickel ores are mined in the fellowing deposits: Elizavetinsk, near Sverdlovsk; Khalilovo, near Orsk; and Malkinsk, in the Northern Caucasus.

- E N D -

- 2 -

CONFIDENTIAL